Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

FID 407: Bosch MEDC17 TC17XX BENCH [SM2 ONLY]

Overview

Family for reading and writing Bosch MEDC17 ECUs

Module: Bosch MEDC17 TC17XX BENCH [SM2 ONLY]

Supported MCUs: TC1724, TC1728, TC1762, TC1766, TC1767, TC1782, TC1792, TC1793, TC1796, TC1797

Supported features

Universal module for Bench reading and writing for Bosch MEDC17 ECUs based on TC17XX MCUs.

Allows reading and writing flash and EEPROM on the bench with auto detection of MCU type and file size. Checksum fix is performed on writing.

Attention!

- Module **works only** with **Scanmatik SM2** or **SM2 Pro**.
- This FID is not suitable for cloning ECU because there are protected OTP sectors. Also sectors (0x10; 0x20) are skipped during writing operation in order to avoid bricking ECUs.
- On some ECUs checksums calculation may take a long time. It depends on the configuration of your computer.
- In case of an identification error, check your connection, and also change the places of the GPT wire.
- All tested adapters with automatic power management with wires for the GPT signal output available by the link below:
  http://archive.powertuner.net/bitbox/help/Adapters.pdf

This manual was last updated on 19.04.2024

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Table of Contents

Alfa Romeo 12

EDC17C69 TC1793 Version 1 12

EDC17C69 TC1793 Version 2 12

EDC17C69 TC1793 Version 3 12

Ashok leyland 13

EDC17CV54 TC1767 13

Aston Martin 14

ME17.8.31 TC1797 14

BAJAJ KTM 15

M17.8.42 TC1762 15

BAW 16

EDC17CV54 TC1767 16

BMW 17

DCU17PC42 TC1724 17

EDC17C06 TC1766 17

EDC17C41 TC1797 17

EDC17C50 TC1797 18

EDC17C76 TC1793 18

EDC17CP02 TC1766 18

EDC17CP09 TC1796 19

EDC17CP45 TC1797 Version 1 19

EDC17CP45 TC1797 Version 2 19

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

EDC17CP49 TC1797 20
ME(V)17.2.1 TC1796 20
MEV17.2 TC1766 20
MEVD17.2 TC1797 21
MEVD17.2.3 TC1793 21

BMW Motorrad 22

ME17.2 TC1797 22
ME17.2.4 TC1793 22

BRP....23

ME17.8.5 TC1762 23

CFMoto....24

ME17.8.10 TC1728....24

China 25

ME17.6.8 TC1762 25
ME17.8.8/17.8.8.1/17U6/UP6 TC1728/1782 25

Citroen 26

EDC17CP11 TC1796 26
ME17.9.53 TC1782....26

Claas....27

EDC17C53 TC1767 Version 1....27
EDC17C53 TC1767 Version 2....27

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Dacia 28

EDC17C42 TC1767 28

EDC17C84 TC1782 28

Deutz 29

EDC17C53 TC1767 Version 1 29

EDC17C53 TC1767 Version 2 29

EDC17CV54 TC1767 29

DongFeng 30

EDC17C63 TC1724 30

EDC17CV54 TC1767 30

Doosan 31

EDC17CV54 TC1767 31

Farmtrac 32

EDC17C63 TC1724 32

Fiat 33

EDC17C69 TC1793 Version 1 33

EDC17C69 TC1793 Version 2 33

EDC17C69 TC1793 Version 3 33

EDC17C84 TC1782 34

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Ford 35

DCU17PC43 TC1724 35

EDC17C10 TC1797 35

EDC17C70 TC1793 35

MED17.0 TC1767 36

MED17.0.1 TC1767 Version 1 36

MED17.0.1 TC1767 Version 2 36

MEDG17.0 TC1797 37

Foton 38

EDC17C63 TC1724 38

Great Wall 39

EDC17C53 TC1767 Version 1 39

EDC17C53 TC1767 Version 2 39

EDC17C63 TC1724 39

GWM 40

EDC17C53 TC1767 Version 1 40

EDC17C53 TC1767 Version 2 40

Haval 41

EDC17C53 TC1767 Version 1 41

EDC17C53 TC1767 Version 2 41

Hino 42

EDC17CV54 TC1767 42

Honda 43

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

EDC17CP06 TC1792 43

Isuzu 44

EDC17C63 TC1724 44

Iveco 45

EDC17C69 TC1793 Version 1 45

EDC17C69 TC1793 Version 2 45

EDC17C69 TC1793 Version 3 45

JAC 46

EDC17C53 TC1767 Version 1 46

EDC17C53 TC1767 Version 2 46

Jeep 47

EDC17C69 TC1793 Version 1 47

EDC17C69 TC1793 Version 2 47

EDC17C69 TC1793 Version 3 47

JLR 48

EDC17CP11 TC1796 48

EDC17CP42 TC1797 48

MED17.0 TC1767 48

MED17.8.31 TC1797 49

MEDC17.9 TC1793 49

JMC 50

EDC17C63 TC1724 50

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

KIA/Hyundai 51

DCU17PC43 TC1724 51

EDC17C08 TC1766 Version 1 51

EDC17C08 TC1766 Version 2 51

EDC17C53 TC1767 Version 1 52

EDC17C53 TC1767 Version 2 52

EDC17C57 TC1793 Version 1 52

EDC17C57 TC1793 Version 2 53

EDC17CP14 TC1796 Version 1 53

EDC17CP14 TC1796 Version 2 53

ME17.9.1 TC1796 54

MEG17.9.22 TC1724 54

Mahindra 55

EDC17C53 TC1767 Version 1 55

EDC17C53 TC1767 Version 2 55

EDC17C63 TC1724 55

Massey Ferguson 56

EDC17C63 TC1724 56

Mercedes-Benz 57

DCU17PC01 TC1766 57

DCU17PC42 TC1724 57

EDC17C42 TC1767 57

EDC17C43 TC1797 58

EDC17CP10 TC1796 58

EDC17CP46 TC1797 58
EDC17CP57 TC1793 Version 1 59
EDC17CP57 TC1793 Version 2 59
MED17.7.1 TC1797 Version 1 59
MED17.7.1 TC1797 Version 2 60
MED17.7.3.1 TC1797 60
MED17.7.5 TC1793 60
MED17.7.7 TC1793 Version 1 61
MED17.7.7 TC1793 Version 2 61

MG 62

EDC17C53 TC1767 Version 1....62
EDC17C53 TC1767 Version 2....62

Mitsubishi Fuso....63

EDC17CV54 TC1767 63

Nissan....64

DCU17PC42 TC1724....64
EDC17C42 TC1767 64
EDC17C84 TC1782 64

Opel 65

EDC17C18 TC1766 65
EDC17C19 TC1792 65
EDC17C42 TC1767 65
EDC17C69 TC1793 Version 1....66
EDC17C69 TC1793 Version 2....66

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

EDC17C69 TC1793 Version 3.....66
EDC17C84 TC1782 67

Peugeot 68

EDC17CP11 TC1796 68
ME17.9.53 TC1782.....68

Polaris 69

M17.8.7 TC1762 69
ME17.9.74 TC1767.....69

Renault.....70

DCU17PC42 TC1724.....70
EDC17C42 TC1767 70
EDC17C84 TC1782 70

SsangYong 71

MED17.9.32 TC1782 71

Suzuki.....72

EDC17C69 TC1793 Version 1.....72
EDC17C69 TC1793 Version 2.....72
EDC17C69 TC1793 Version 3.....72
ME17.9.5 TC1762 73
ME17.9.51 TC1762.....73
ME17.9.6 TC1767 73
ME17.9.64 TC1724.....74

Toyota 75

EDC17CP07 TC1766 75
EDC17CP37 TC1766 75
ME17.9.52 TC1782 75
ME17.9.53 TC1782 76

VAG 77

EDC17C46 TC1767 77
EDC17C54 TC1797 77
EDC17C64 TC1797 77
EDC17C74 TC1793 Version 1 78
EDC17C74 TC1793 Version 2 78
EDC17CP14 TC1796 Version 1 78
EDC17CP14 TC1796 Version 2 79
EDC17CP20 TC1796 79
EDC17CP44 TC1797 79
EDC17U01 TC1766 80
INVCON 2.3 TC1797 80
ME17.5.22 TC1724 80
ME17.5.24 TC1724 81
ME17.5.26 TC1724 81
ME17.5.6 TC1767 81
MED17.1 TC1796 82
MED17.1.21 TC1793 Version 1 82
MED17.1.21 TC1793 Version 2 82
MED17.1.27 TC1793 83
MED17.1.6 TC1797 Version 1 83

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

MED17.1.6 TC1797 Version 2 83
MED17.5 TC1766 84
MED17.5.1 TC1796 84
MED17.5.2 TC1767 84
MED17.5.20 TC1766 85
MED17.5.21 TC1782 85
MED17.5.25 TC1782 85
MED17.5.5 TC1766 86

Valtra 87

EDC17C63 TC1724 87
EDC17CV54 TC1767 87

VAZ/UAZ 88

ME17.9.7 TC1762 Version 1 88
ME17.9.7 TC1762 Version 2 88

Volvo 89

MED17.0 TC1767 89

Yanmar 90

EDC17CV54 TC1767 90

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Alfa Romeo

EDC17C69 TC1793 Version 1



EDC17C69 TC1793 Version 2



EDC17C69 TC1793 Version 3



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Ashok leyland

EDC17CV54 TC1767



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Aston Martin

ME17.8.31 TC1797



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

BAJAJ KTM

M17.8.42 TC1762



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

BAW

EDC17CV54 TC1767



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

BMW

DCU17PC42 TC1724



EDC17C06 TC1766



EDC17C41 TC1797



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

EDC17C50 TC1797



EDC17C76 TC1793



EDC17CP02 TC1766



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

EDC17CP09 TC1796



EDC17CP45 TC1797 Version 1



EDC17CP45 TC1797 Version 2



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

EDC17CP49 TC1797



ME(V)17.2.1 TC1796



MEV17.2 TC1766



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

MEVD17.2 TC1797



MEVD17.2.3 TC1793



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

BMW Motorrad

ME17.2 TC1797



ME17.2.4 TC1793



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

BRP

ME17.8.5 TC1762



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

CFMoto

ME17.8.10 TC1728



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

China

ME17.6.8 TC1762



ME17.8.8/17.8.8.1/17U6/UP6 TC1728/1782



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Citroen

EDC17CP11 TC1796



ME17.9.53 TC1782



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Claas

EDC17C53 TC1767 Version 1



EDC17C53 TC1767 Version 2



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Dacia

EDC17C42 TC1767



EDC17C84 TC1782

Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Deutz

EDC17C53 TC1767 Version 1



EDC17C53 TC1767 Version 2



EDC17CV54 TC1767



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

DongFeng

EDC17C63 TC1724



EDC17CV54 TC1767





Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Doosan

EDC17CV54 TC1767



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Farmtrac

EDC17C63 TC1724



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Fiat

EDC17C69 TC1793 Version 1



EDC17C69 TC1793 Version 2



EDC17C69 TC1793 Version 3



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

EDC17C84 TC1782

Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Ford

DCU17PC43 TC1724



EDC17C10 TC1797



EDC17C70 TC1793



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

MED17.0 TC1767



MED17.0.1 TC1767 Version 1



MED17.0.1 TC1767 Version 2



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

MEDG17.0 TC1797



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Foton

EDC17C63 TC1724



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Great Wall

EDC17C53 TC1767 Version 1



EDC17C53 TC1767 Version 2



EDC17C63 TC1724



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

GWM

EDC17C53 TC1767 Version 1



EDC17C53 TC1767 Version 2



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Haval

EDC17C53 TC1767 Version 1



EDC17C53 TC1767 Version 2



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Hino

EDC17CV54 TC1767



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Honda

EDC17CP06 TC1792



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Isuzu

EDC17C63 TC1724



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Iveco

EDC17C69 TC1793 Version 1



EDC17C69 TC1793 Version 2



EDC17C69 TC1793 Version 3



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

JAC

EDC17C53 TC1767 Version 1



EDC17C53 TC1767 Version 2



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Jeep

EDC17C69 TC1793 Version 1



EDC17C69 TC1793 Version 2



EDC17C69 TC1793 Version 3



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

JLR

EDC17CP11 TC1796



EDC17CP42 TC1797



MED17.0 TC1767



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

MED17.8.31 TC1797



MEDC17.9 TC1793



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

JMC

EDC17C63 TC1724



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

KIA/Hyundai

DCU17PC43 TC1724



EDC17C08 TC1766 Version 1





EDC17C08 TC1766 Version 2





Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

EDC17C53 TC1767 Version 1



EDC17C53 TC1767 Version 2



EDC17C57 TC1793 Version 1



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

EDC17C57 TC1793 Version 2



EDC17CP14 TC1796 Version 1



EDC17CP14 TC1796 Version 2



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

ME17.9.1 TC1796



MEG17.9.22 TC1724



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Mahindra

EDC17C53 TC1767 Version 1



EDC17C53 TC1767 Version 2



EDC17C63 TC1724



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Massey Ferguson

EDC17C63 TC1724



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Mercedes-Benz

DCU17PC01 TC1766



DCU17PC42 TC1724



EDC17C42 TC1767



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

EDC17C43 TC1797



EDC17CP10 TC1796



EDC17CP46 TC1797



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

EDC17CP57 TC1793 Version 1



EDC17CP57 TC1793 Version 2



MED17.7.1 TC1797 Version 1



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

MED17.7.1 TC1797 Version 2



MED17.7.3.1 TC1797



MED17.7.5 TC1793



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

MED17.7.7 TC1793 Version 1



MED17.7.7 TC1793 Version 2



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

MG

EDC17C53 TC1767 Version 1



EDC17C53 TC1767 Version 2



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Mitsubishi Fuso

EDC17CV54 TC1767



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Nissan

DCU17PC42 TC1724



EDC17C42 TC1767



EDC17C84 TC1782

Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Opel

EDC17C18 TC1766



EDC17C19 TC1792



EDC17C42 TC1767



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

EDC17C69 TC1793 Version 1



EDC17C69 TC1793 Version 2



EDC17C69 TC1793 Version 3



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

EDC17C84 TC1782

Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Peugeot

EDC17CP11 TC1796



ME17.9.53 TC1782



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Polaris

M17.8.7 TC1762



ME17.9.74 TC1767



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Renault

DCU17PC42 TC1724



EDC17C42 TC1767



EDC17C84 TC1782

Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

SsangYong

MED17.9.32 TC1782



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Suzuki

EDC17C69 TC1793 Version 1



EDC17C69 TC1793 Version 2



EDC17C69 TC1793 Version 3



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

ME17.9.5 TC1762



ME17.9.51 TC1762



ME17.9.6 TC1767



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

ME17.9.64 TC1724



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Toyota

EDC17CP07 TC1766



EDC17CP37 TC1766



ME17.9.52 TC1782



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

ME17.9.53 TC1782



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

VAG

EDC17C46 TC1767



EDC17C54 TC1797



EDC17C64 TC1797



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

EDC17C74 TC1793 Version 1



EDC17C74 TC1793 Version 2



EDC17CP14 TC1796 Version 1



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

EDC17CP14 TC1796 Version 2



EDC17CP20 TC1796



EDC17CP44 TC1797



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

EDC17U01 TC1766



INVCON 2.3 TC1797



ME17.5.22 TC1724



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

ME17.5.24 TC1724



ME17.5.26 TC1724



ME17.5.6 TC1767



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

MED17.1 TC1796



MED17.1.21 TC1793 Version 1



MED17.1.21 TC1793 Version 2



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

MED17.1.27 TC1793



MED17.1.6 TC1797 Version 1



MED17.1.6 TC1797 Version 2



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

MED17.5 TC1766



MED17.5.1 TC1796



MED17.5.2 TC1767



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

MED17.5.20 TC1766



MED17.5.21 TC1782



MED17.5.25 TC1782



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

MED17.5.5 TC1766



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Valtra

EDC17C63 TC1724



EDC17CV54 TC1767





Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

VAZ/UAZ

ME17.9.7 TC1762 Version 1



ME17.9.7 TC1762 Version 2



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Volvo

MED17.0 TC1767



Ground Power Can-H Can-L GPT-1 GPT-2

Attention! Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

Yanmar

EDC17CV54 TC1767



Ground Power Can-H Can-L GPT-1 GPT-2